DRC

1. Clock Rules (C Rules)

1.1 C1

When all clocks are at their off state as defined with the add_clocks command, all clock inputs (including sets and resets) of scan and non-scan cells must be at their off state.
For non-scan cell violations, the tool converts these to TIEX.